




PLAN OF TREUERS WORKINGS. MOONTA MINES

SCALE 6 FATHOMS TO ONE INCH.

SECTION 933.



TREUERS SHAFT

TREUERS AIR SHAFT

TREUERS S. SHAFT.



WALLAROO
DRAWN BY W. H. HARRIS
EXP.